

HISTORIC AMERICAN ENGINEERING SURVEY

RECORDED

HAER
IND
90-BLUFF.V,
1-

INDEX TO PHOTOGRAPHS

Wells County Bridge No. 74
On County Road 400 West over Rock Creek
Approximately 6.5 miles west of Bluffton
Wells County
Indiana

HAER No. IN-94

Photographer; All views, Camille B. Fife & Thomas W. Salmon II, February/March,
1997 The Westerly Group, Inc.

- IN-94-01 A LONG VIEW, LOOKING WEST FROM THE SOUTHEAST BANK OF
ROCK CREEK DITCH SHOWING THE EAST SIDE OF THE BRIDGE.
- IN-94-02 LOOKING EAST, A MEDIUM VIEW OF THE WEST SIDE OF THE
STRUCTURE.
- IN-94-03 LOOKING SOUTH THROUGH THE ROADWAY, FROM THE NORTH
PORTAL.
- IN-94-04 AN IMAGE LOOKING NORTHWEST FROM THE SOUTHEAST
APPROACH TO THE BRIDGE.
- IN-94-05 A VIEW LOOKING NORTHWEST FROM THE SOUTHEAST BANK,
SHOWING THE EAST ABUTMENT, THE BRIDGE STRUCTURE AND
BOTH BANKS.
- IN-94-06 A PHOTOGRAPH LOOKING WEST, TAKEN FROM THE ROADWAY OF
THE BRIDGE, SHOWING A DOWNSTREAM VIEW OF ROCK CREEK
DITCH.
- IN-94-07 A VIEW LOOKING NORTHEAST FROM THE SOUTH BANK, SHOWING
THE BRIDGE AND ITS NORTHERN ABUTMENT.
- IN-94-08 LOOKING DUE NORTH FROM THE SOUTH BANK, A VIEW OF THE
NORTH ABUTMENT AND THE UNDERSIDE OF THE BRIDGE DECK.
- IN-94-09 LOOKING NORTHWEST, A VIEW OF THE NORTH ABUTMENT, THE
DITCH AND THE EAST SIDE OF THE STRUCTURE FROM BELOW.
- IN-94-10 AN IMAGE, LOOKING DUE NORTH OF THE BRIDGE DECK,
SHOWING THE LAYERS OF GRAVEL, ASPHALT AND TIMBER.

Index to Photographs
Wells County Bridge No. 74
HAER No. IN-94 (Page 2)

- IN-94-11 A DETAIL VIEW, LOOKING NORTH, OF THE WEST INCLINED END POST, AND OF THE PIN CONNECTION OF THE SOUTHWESTERN VERTICAL MEMBER.

- IN-94-12 A DETAIL VIEW OF THE NORTHEASTERN END POST, LOOKING SOUTH, SHOWING THE MANUFACTURER'S MARK, "CARNEGIE".

- IN-94-13 A DETAIL VIEW, LOOKING EAST FROM THE WEST SIDE OF THE BRIDGE, OF THE LOWER PIN CONNECTION OF A TYPICAL VERTICAL MEMBER. VISIBLE ARE THE EYEBARS, HANGERS, "I" SECTION , SWAY BARS AND WOOD DECKING.

- IN-94-14 A VIEW LOOKING SOUTHEAST OF A PORTION OF THE LIMESTONE ABUTMENT, THE UNDERSIDE OF THE INCLINED END POST AND A PLATE USED TO ATTACH THE STRUCTURE TO THE ABUTMENT.

- IN-94-15 A DETAIL VIEW, LOOKING WEST FROM THE SOUTHEAST BANK OF THE DITCH, SHOWING THE EAST SIDE OF ONE OF THE ABUTMENTS. MOST JOINTS LOOK DRY, BUT WERE ORIGINALLY FILLED WITH MORTAR.

- IN-94-16 A DETAIL VIEW, LOOKING EAST FROM THE ROADWAY OF THE BRIDGE, SHOWING THE PINNED CONNECTION OF THE SOUTHEASTERN VERTICAL MEMBER, THE LATTICE RAIL, AND PART OF THE BRACING.

Key to Photographs
Wells County Bridge No. 74
HAER No. IN-94 (Page 3)

